

Matrox® Release Notes

Matrox® Extio 3 Series

Software version 2.01.02

20265-401-0006
August 10, 2020

Overview

This document describes the current release (version 2.01.00) of the Matrox Extio 3 firmware, OSD (On-Screen Display), and Extio Central Manager software. Matrox provides these notes to describe new features, bug fixes, and improvements to Extio 3 Series hardware and software.

First-time setup of point-to-point mode

When using your devices *out of the box* and setting them up for the first time, the on-screen display (OSD) on the Receiver (Rx) device show an initial log-in screen.

To enable point-to-point mode, click **Enable Point-to-Point mode** on the log-in screen. (Point-to-point uses a direct link between the Transmitter (Tx) and Receiver (Rx) devices, without going through a network switch.) Selecting this option reboots your devices to complete the configuration process.

For more information on performing a configuration reset, see your Matrox Extio 3 Series User Guide.

New features

- Added support for Yokogawa Centum VP Keyboard.

Notes and limitations

- **Firmware Updater** – To update the firmware, the Updaterfromhost.exe file installs a USB mass storage device on the Extio 3 transmitter unit. On certain systems, the Group Policy Object (GPO) may prevent the Updaterfromhost.exe file from installing the USB mass storage device. To allow the installation of this Matrox device, you may need to apply an exception to your GPO rules (for example, by adding USBSTOR\DiskMatrox__Virtual_Storage_1.00). For more information on modifying your GPO rules, contact your system administrator.
- **Extio Central Manager** – Installing new units with or updating units to the 2.01.02 firmware while the 1.00.06 Extio Central Manager is still running will result in the updated units not listed, or listed as lost, in the UI. To correct this, uninstall the 1.00.06 version and install the 2.01.02 version of the Extio Central Manager software. [1781]
- **Firmware** – Update your Tx and Rx devices to firmware version 2.01.02.002 before using your devices. To update new units or units already configured in Networked mode, use the *UpdaterOverNetwork* program to update your units.

If you're updating units already configured in point-to-point mode, use the *UpdaterFromHost* program to update your units.

- **Firmware** – To ensure proper functioning of your devices, the firmware version installed on your Tx and Rx devices must match.
- **Firmware** – When updating your firmware, make sure your Extio 3 setup is using either point-to-point mode or networked mode, and not a mix of operating modes. [2277]
- The following features aren't yet enabled:
 - Local output support (Video out) on the Tx device is expected in an upcoming release.
 - The USB connectors on the front of the Tx device are currently disabled.
- **Power management** – When using an XTO3-N3408CTX or XTO3-N3208CTX card, power management on the host system isn't currently supported. [1076]
- **Mura IPX Series** – This firmware release isn't compatible with Mura IPX Series software version 3.00.00 or older.
- If all of your devices are seen and configurable in Extio Central Manager, but the OSD of an RX device doesn't reflect the connections that were configured in the **Connection Broker**, verify that the devices all have a valid IP address and that the network ports are accessible.
- **Dell™ Precision™ Rack R7920 Workstation or PowerEdge™ R740** – If your XTO3-N3408CTX or XTO3-N3208CTX card is installed in PCIe slot 1, that slot may not work. We recommend using a slot other than slot 1. If you need to use slot 1, you need to disable that slot. To disable the slot, enter the **System Bios**, then click **Integrated Devices** → **Slot disablement**, and make sure the slot is marked as **Disabled**. When you're done, save your changes and reboot your system. [803]
- **USB devices** – Some older keyboard and mouse combos that use a Bluetooth® mini-receiver aren't supported in Networked mode. These devices may be used in point-to-point mode but need the manufacturer's device drivers. [1262]
- On some GPUs, outputs may have temporal dithering enabled. This may result in blocky images. To avoid this make sure your GPU settings are configured to use RGB as the output color format and the maximum level (i.e. Full) as the output dynamic range. [1632]
- Hot plugging SFP modules isn't supported. A reboot might be required after adding an SFP module to your device to ensure proper detection and functionality. [1963]

- **Random loss of Sync while in point-to-point mode** – You may lose monitor sync briefly if the display refresh rate reported in the OSD doesn't match the refresh rate of your display. For example, this may occur if the GPU reports a refresh rate of 59 Hz. Setting the refresh rate to 60 Hz should solve the issue.
- If you're using an adapter to connect your monitor to your Extio 3 device, only active adapters (sold separately) are supported. Passive adapters aren't supported.

Known issues

- After adding a new Tx device and configuring it using Extio Central Manager software, it can take up to 45 seconds for the new Tx device to appear in the OSD as an available connection option for the Rx.
- **USB** – Switching while using USB 2.0 devices (ie. USB keys, hard drives, scanners, etc...) isn't supported and may result in lost data or devices (need to unplug/replug device to redetect). We recommend stopping all USB 2.0 transfers before switching.
- **USB** – Loss of connection between a Tx and an Rx (power interruption, network failure or fiber failure) while doing USB 2.0 transfers may result in lost devices (need to unplug/replug device to redetect) or lost data.
- **Firmware Updater** – When the Updater has completed, a message may appear stating that not all Extio 3 Series devices were properly updated. If this occurs, close the updater and re-launch it. If the devices report that they need an update, proceed with the update. If the update fails again, please contact Matrox Technical Support.
- **Firmware Updater** – While performing an update in point-to-point mode using firmware version 2.01.02.000 and higher, a message will appear on your screens showing the progress of the update. Your displays will go blank (black) for short periods during the process, the displays will return once the update process is complete.
- After updating your firmware, one of the displays connected to your Rx may be lost. To fix this, we recommend you turn off the monitor and then turn it on again.
- After rebooting your Tx or Rx, one of your displays may be lost. To fix this, we recommend you turn off the monitor, and then turn it on again.
- **Point-to-point mode** – When rebooting your source system or host system, the connection between the Tx and Rx devices may be lost. To fix this, we recommend you use the **Refresh connection** option in the OSD.
- **Wake-on-LAN** – N3408CTX and N3208CTX cards support wake-on-LAN.

- **Wake-on-LAN** – When using the wake-on-LAN feature with an N3408CTX or N3208CTX card installed in HP Z440 workstations, the devices may become unresponsive and require the system to be rebooted. [1819]

Contact us

The Matrox web site has product literature, press releases, technical material, a sales office list, trade show information, and other relevant material. Visit us at www.matrox.com/graphics.

If you have any questions or comments about our products or solutions, contact us at www.matrox.com/graphics/contact.

Matrox values your business and offers professional support for your Matrox product. For more information, contact your Matrox representative or our technical support at kvmsupport@matrox.com.

Disclaimer

Information in this document may contain technical inaccuracies or typographical errors. Information may be changed or updated without notice. Matrox reserves the right to make improvements and/or changes in the products, programs and/or specifications described in this information at any time without notice. All trademarks and trade names, service marks and logos referenced herein belong to their respective owners.

Dell, Precision, and PowerEdge are trademarks or registered trademarks of Dell Inc. or its subsidiaries.

Microsoft, Windows, and Active Directory are registered trademarks of Microsoft Corporation in the United States and/or other countries.

Copyright © 2020 Matrox is a trademark of Matrox Electronic Systems Ltd. All rights reserved.

Matrox Graphics Inc.

1055 Saint Regis Boulevard
Dorval, Quebec, Canada
H9P 2T4

(514) 822-6000

graphics@matrox.com
www.matrox.com/graphics

matrox[®]
Graphics for Professionals