22 April 2003

Dear Customer:

Please make sure you follow the installation instructions for both the serial and parallel ports if the product you are trying to install has serial and parallel ports (products 9835, 9735).

Regards,

Sales